

FIG.1A




FIG.1B





FIG.1C




2/18

FIG.2

T	Y 3LL, 3HL-LH-HH, 2HL-LH-HH, 1HL-LH-HH Cb 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH Cr 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH	T	Y 3LL, 3HL-LH-HH, 2HL-LH-HH, 1HL-LH-HH Cb 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH Cr 3LL, 3HL-LH-HH 2HL-LH-HH, 1HL-LH-HH
T=0	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 1 0, 0 0 0, 0 0 0, 0 0 0	T=399	1, 1 1 3, 4 4 6, 101017 9, 101013, 141418, 202027 8, 9 9 11, 121216, 181823
T=1	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 2 0, 0 0 0, 0 0 0, 0 0 0	T=400	1, 1 1 3, 4 4 6, 101017 9, 101013, 141418, 202027 8, 9 9 11, 121216, 181823
T=2	0, 0 0 0, 0 0 0, 0 0 0 0, 0 0 0, 0 0 0, 0 0 3 0, 0 0 0, 0 0 0, 0 0 0	.	.
.	.	.	.
.	.	T=499	.
T=99	0, 0 0 0, 0 0 0, 0 0 6 0, 0 0 3, 4 4 8, 101017 0, 0 0 1, 2 2 6, 7 7 13	T=500	.
T=100	0, 0 0 0, 0 0 0, 0 0 7 0, 0 0 3, 4 4 8, 101017 0, 0 0 1, 2 2 6, 7 7 13	.	.
.	.	.	.
.	.	T=1000	.
T=199	0, 0 0 0, 0 0 0, 5 5 11 3, 4 4 7, 8 8 13, 151521 2, 3 3 6, 7 7 10, 121217	.	.
T=200	0, 0 0 0, 0 0 0, 5 5 11 3, 4 4 7, 8 8 13, 151522 2, 3 3 6, 7 7 10, 121217	T=1500	.
.	.	.	.
.	.	.	.
T=299	0, 0 0 0, 1 1 4, 8 8 14 6, 7 7 10, 111216, 181825 6, 6 6 9, 101013, 151520	.	.
T=300	0, 0 0 0, 1 1 4, 8 8 14 6, 7 7 10, 121216, 181825 6, 6 6 9, 101013, 151520	.	.
.	.	.	.
.	.	.	.
.	.	.	.


4/18

FIG.4



5/18

FIG.5



6/18
FIG.6




FIG.7





FIG.8



8/18

FIG.9




FIG. 10





FIG.11



11/18

FIG.12





FIG.13



13/18

FIG.14




FIG.15




FIG. 16





FIG.17



17/18

FIG.18

